

UNCLASSIFIED

AD NUMBER

AD366760

CLASSIFICATION CHANGES

TO: unclassified

FROM: confidential

LIMITATION CHANGES

TO:

Approved for public release, distribution unlimited

FROM:

Notice: Release only to U. S. Government Agencies is authorized. Other certified requesters shall obtain release approval from Director, Defense Atomic Support Agency, Washington, D. C. 20301.

AUTHORITY

DSWA ltr., 18 Apr 1997; DSWA ltr., 18 Apr 1997

THIS PAGE IS UNCLASSIFIED

XRD

81

9

CONFIDENTIAL
Security Information

BUREAU OF SHIPS
TECHNICAL INSPECTION REPORT

Classification (Cancelled) (Changed to Security Information)
By Authority of JOINT CHIEFS OF STAFF JCS 1795/36 DATED 15 APRIL 1949
By John H. Deyelle Date 24 SEP 1958

U. S. GOVERNMENT AGENCIES MAY OBTAIN COPIES OF THIS REPORT DIRECTLY
FROM DDC. OTHER AGENCIES SHALL REQUEST THROUGH

U.S.S. LCM - 1

TEST ABLE [U].8

Director
Defense Atomic Support Agency
Washington, D. C. 20301

AD NO. 346760

DDC FILE COPY

CONFIDENTIAL
Security Information

6

OPERATION CROSSROADS

DIRECTOR OF SHIP MATERIAL

JOINT TASK FORCE ONE

11

SECRET

7, 12 32p. 14 XRD-81

CONFIDENTIAL

DDC
NOV 24 1955
RESOLVED

TISA &
REG. NO. 50

GROUP 1
Declassified on 12 year intervals;
Not automatically declassified.
1 JAN 1965

mb

CONFIDENTIAL

BUREAU OF SHIPS GROUP
TECHNICAL INSPECTION REPORT

IT IS REQUESTED THAT NO DISCUSSION OF THIS REPORT DIRECTLY
FROM BUREAU OF SHIPS GROUP BE REQUESTED THROUGH

Reference Atomic Support Agency
Washington, D. C. 20301

*This document contains information affecting the National
Defense of the United States within the meaning of the
Espionage Laws, Title 18, U. S. C., Section 793 and 794.
Its transmission or the revelation of its contents in any
manner to an unauthorized person is prohibited by law.*

APPROVED:

F.X. Forest,
Captain, U.S.N.

SECRET

USS LCM-1

Page 1 of 32 Pages

CONFIDENTIAL

GROUP 3
1 JAN 1965
Downgraded at 12 month intervals;
Not automatically declassified.

TABLE OF CONTENTS

	PAGE NO.
Overall Summary of Damage - - - - -	3
Hull Technical Inspection Report (Section I) - - - - -	6
Machinery Technical Inspection Report (Section II) - -	12
Electrical Technical Inspection Report (Section III) - -	18
Photographic Section (Section IV) - - - - -	25

SECRET

USS LCM-1

TECHNICAL INSPECTION REPORT

OVERALL SUMMARY

I. Target Condition After Test.

(a) Drafts after test, general areas of flooding, sources.

No draft marks are fitted. Some flooding has occurred through the stern tubes which were leaking before the test. Although the craft was afloat the day after the test when inspected, three days later she was floating with four feet of the bow ramp out of water.

(b) Structural Damage.

The bow ramp was blown open. The ramp cables and special chain lashings which were installed for the test parted. The deck over the engine compartment is dished about two inches. The bulwarks around the conning station and those outboard of the tank well are slightly deflected.

(c) Other damage.

There was no damage to machinery during Test A except for flooding. All electrical equipment on the vessel was rendered inoperable by flooding. Storage batteries were partly dislodged from their racks.

II. Forces evidenced and effects noted.

(a) Heat.

Paint on deck was slightly scorched and blistered.

(b) Fires and Explosions.

None.

SECRET

USS LCM-1

(c) Shock.

Shock effect was noted by storage batteries partly dislodged from their racks.

(d) Pressure.

Air blast blew open the bow ramp and caused deflection of topside bulwarks and the deck above the engine compartment.

(e) Effects peculiar to the Atomic Bomb.

None.

III. Effects of Damage.

(a) Effect on machinery, electrical, and ship control.

The deflection of the deck above the engine compartment caused misalignment of the steering mechanism which now operates with considerable difficulty.

(b) Effect on gunnery and fire control.

Not applicable.

(c) Effect on watertight integrity and stability.

None.

(d) Effect on personnel and habitability.

Personnel aboard would probably have been injured or killed by blast and heat.

(e) Effect on fighting efficiency.

Fighting efficiency is decreased by failure of the bow ramp securing mechanism.

SECRET

USS LCM-1

IV. General Summary of Observers' Impressions and Conclusions.

This craft stood up very well considering the proximity to the burst.

V. Preliminary General or Specific Recommendations of Inspection Group.

Provision should be made for a more adequate securing device for the bow ramp.

SECRET

Page 5 of 32 Pages

USS LCM-1

TECHNICAL INSPECTION REPORT

SECTION I - HULL

GENERAL SUMMARY OF HULL DAMAGE

I. Target Condition After Test.

(a) Drafts after test, general areas of flooding, sources.

No draft marks are fitted. Some flooding has occurred through the stern tubes which were leaking before the test.

(b) Structural damage.

The bow ramp was blown open. The ramp cables and special chain lashings which were installed for the test parted. The deck over the engine compartment is dished about two inches. The bulwarks around the conning station and those outboard of the tank well are slightly deflected.

(c) Other damage.

Not observed.

II. Forces Evidenced and Effects Noted.

(a) Heat.

There was some slight blistering of the deck paint.

(b) Fires and explosions.

None.

SECRET

USS LCM 1

(c) Shock.

None.

(d) Pressure.

Air blast blew open the bow ramp and caused deflection of topside bulwarks and the deck above the engine compartment.

(e) Effects peculiar to the atom bomb.

None.

III. Results of Test on Target.

(a) Effect on machinery, electrical, and ship control.

The deflection of the deck above the engine compartment caused misalignment of the steering mechanism which now operates with considerable difficulty.

(b) Effect on gunnery and fire control.

Not applicable.

(c) Effect on watertight integrity and stability.

None.

(d) Effect on personnel and habitability.

Personnel aboard would probably have been injured by blast and heat.

(e) Effect on fighting efficiency.

Fighting efficiency is decreased by failure of the bow ramp securing mechanism.

SECRET

USS LCM 1

IV. Summary of Observers' Impressions and Conclusions.

This craft stood up very well considering the proximity to the burst.

V. Preliminary Recommendations.

Provision should be made for a more adequate securing device for the bow ramp.

SECRET

USS LCM 1

DETAILED DESCRIPTION OF HULL DAMAGE

A. General Description of Hull Damage.

This craft sustained moderate deflection of topside plating and had the bow ramp blown open as the result of air blast.

B. Superstructure.

The overhead of the engine compartment is dished about one foot (Photo 1899-11, page 28). The bulwarks around the conning station are pushed forward and the after bulwark is dished about 3 inches. An access plate in the forward bulwark which was secured by only four bolts has come completely off (Photos 1899-11, 12, 2816-7; pages 28 to 30). The bow ramp was blown open. This was secured by the regular ramp operating cables and by special chain lashings. The bulwarks on either side of the tank were bent slightly to starboard (Photos 96-9, 1746-5; pages 31 and 32).

C. Turrets, Guns and Directors.

Not applicable.

D. Torpedo Mounts, Depth Charge Gear.

Not applicable.

E. Weather Deck.

The weather deck aft is deflected downward slightly, just forward of the after bulkhead of the engine compartment.

F. Exterior Hull.

No damage.

G. Interior Compartments (above waterline).

No damage.

SECRET

USS LCM 1

H. Armor Decks and Miscellaneous Armor.

Not applicable.

I. Interior Compartments (below waterline).

No damage.

J. Underwater Hull.

No damage.

K. Tanks.

No damage.

L. Flooding.

This craft had considerable stern tube leakage before the test. The craft was afloat when boarded on the day after Test A (Photo 1859-2, page 26). It subsequently sank because of accumulated leakage from this source.

M. Ventilation.

Not applicable.

N. Ship Control.

The deflection of the deck above the engine compartment caused misalignment of the steering mechanism. Considerable difficulty would be experienced in steering the craft.

O. Fire Control.

Not applicable.

SECRET

USS LCM 1

P. Ammunition Behavior.

Not applicable.

Q. Ammunition Handling.

Not applicable.

R. Strength.

No damage.

S. Miscellaneous.

No comment.

SECRET

USS LCM 1

TECHNICAL INSPECTION REPORT

SECTION II - MACHINERY

GENERAL SUMMARY OF MACHINERY DAMAGE

I. Target Condition After Test.

- (a) Drafts after test; list; general areas of flooding, sources.

No data taken by machinery group at the time of inspection, the day after the test. Three days later the craft was floating with about four feet of the bow ramp out of the water.

- (b) Structural damage.

No comment.

- (c) Other damage.

There was no damage to machinery during test. A except for flooding which could have been controlled had the crew been aboard.

II. Forces Evidenced and Effects Noted.

- (a) Heat.

Paint on deck was scorched and blistered but a visual inspection showed no damage to the machinery.

- (b) Fires and explosions.

No evidence.

- (c) Shock.

No evidence.

SECRET

USS LCM 1

(d) Pressure.

No comment.

(e) Any effects apparently peculiar to the atom bomb.

None.

III. Effects of Damage.

(a) Effect on machinery, electrical, and ship control.

Test A had no apparent effect on the machinery of this vessel although secondary damage (flooding of the machinery space) rendered the entire machinery room inoperable.

(b) Effect on gunnery and fire control.

No comment.

(c) Effect on watertight integrity and stability.

No comment.

(d) Effect on personnel and habitability.

All personnel would probably have been killed by blast pressure.

(e) Total effect on fighting efficiency.

After flooding of the machinery space the fighting efficiency of this vessel was reduced to zero.

IV. General Summary of Observers' Impressions and Conclusions.

The vessel would have been lost at sea. It is believed all personnel would have been killed by the blast and progressive flooding would have sunk the ship.

SECRET

USS LCM 1

V. Any Preliminary General or Specific Recommendations
of the Inspecting Group.

None.

SECRET

USS LCM 1

DETAILED DESCRIPTION OF MACHINERY DAMAGE

A. General Description of Machinery Damage.

(a) Overall condition.

A visual inspection revealed no direct damage to the machinery of this vessel although secondary damage caused by flooding of the machinery space, rendered all machinery in this space inoperable.

(b) Areas of major damage.

The machinery space.

(c) Primary cause of damage.

Flooding.

(d) Effect of target test on overall operation of machinery plant.

Ship's service generators and propulsion machinery inoperable due to flooding.

B. Boilers.

Not applicable.

C. Blowers.

Not applicable.

D. Fuel Oil Equipment.

Not applicable.

E. Boiler Feedwater Equipment.

Not applicable.

SECRET

USS LCM 1

F. Main Engines.

There were no indications of direct damage from test A although flooding rendered them inoperable.

G. Reduction Gears.

The reduction gears are a component part of the main engines.

H. Shafting and Bearings.

There was no evidence that the target test had affected the shafts and bearings.

I. Lubrication System.

The lubrication system is an integral part of the main engines and is so treated by this report.

J. Condensers and Air Ejectors.

Not applicable.

K. Pumps.

There was no evidence of change in condition to the pumps which could be traced to the target test.

L. Auxiliary Generators.

Not applicable.

M. Propellers.

There was no indications of damage caused by test A.

N. Distilling Plant.

Not applicable.

SECRET

USS LCM 1

O. Refrigerating Plant.

Not applicable.

P. Winches, Windlasses and Capstans.

The ramp winches were not affected by the target test.

Q. Steering Engine.

Not applicable.

R. Elevators, Ammunition Hoists, Etc.

Not applicable.

S. Ventilation (Machinery).

Not applicable.

T. Air Compressors.

Not applicable.

U. Diesels (Generators and Boats).

Not applicable.

V. Piping.

The piping of bilge drain and fuel systems were in poor condition previous to test A. There are no present indications that their condition was affected by the target test.

W. Miscellaneous.

Not applicable.

SECRET

USS LCM 1

TECHNICAL INSPECTION REPORT

SECTION III - ELECTRICAL

GENERAL SUMMARY ELECTRICAL DAMAGE

I. Target Condition After Test.

(a) Drafts after test; list; general areas of flooding, sources.

1. The LCM 1 was floating with about four feet of the bow out of water three days after the test.

2. Sources of flooding were probably through stern tubes and open bow ramps.

(b) Structural damage.

Structural failures caused flooding of all electrical equipment on the vessel.

(c) Other damage.

All electrical equipment on the vessel was rendered inoperable by flooding. Storage batteries were partly dislodged from their racks.

II. Forces Evidenced and Effects Noted.

(a) Heat.

Heat was evidenced by scorched insulation on exposed electric cables.

(b) Fires and explosions.

There was no evidence of electrical damage due to fires or explosions on the vessel.

SECRET

U. S. S. LCM-1

(c) Shock.

Shock effect was noted by storage batteries partly dislodged from their racks.

(d) Pressure.

Pressure was noted by deck failure and distorted structure in way of steering mechanism. Blast pressure was noted by the carrying away of the steering compass.

(e) Any effects apparently peculiar to the atom bomb.

Scorched insulation on exposed electric cable was the only effect noted peculiar to the atom bomb.

III. Effect of Damage.

(a) Effect on electrical machinery and ship control.

All electrical equipment was rendered inoperative by flooding. Propulsion engines could not have been started without new starting batteries and motors. Ship control was affected by loss of the steering compass.

(b) Effect on gunnery and fire control.

Not applicable.

(c) Effect on water-tight integrity and stability.

Water-tight integrity and stability were not affected by electrical damage.

(d) Effect on personnel and habitability.

Electrical damage had no effect on personnel or habitability. Personnel would have been killed by blast pressure and radiation.

SECRET

U. S. S. LCM-1

(e) Total effect on fighting efficiency.

Fighting efficiency was reduced to zero by flooding of all electrical equipment and machinery.

IV. General Summary of Observer's Impressions and Conclusions.

The vessel was rendered completely inoperative by flooding of the entire machinery space. Electrical equipment other than the steering compass would apparently have been operable except for flooding. The shock apparently did no damage to electrical equipment other than to partially dislodge some of the engine starting batteries.

V. Recommendations.

None. It appears that the present electrical equipment will withstand any condition imposed by the test which will not render the vessel inoperable from other causes.

SECRET

U. S. S. LCM-1

DETAILED DESCRIPTION OF ELECTRICAL DAMAGE

A. General Description of Electrical Damage.

(a) Overall condition.

The electric plant is completely inoperable due to total flooding.

(b) Areas of major damage.

The vessel was almost entirely submerged.

(c) Primary causes of damage in each area of major damage.

Flooding due to structural damage from blast was the primary cause of the damage.

(d) Effect of target test on overall operation of electric plant.

(1) Ship's service generator plant - not applicable.

(2) Engine and boiler auxiliaries - Totally inoperable due to flooding.

(3) Electric propulsion - not applicable.

(4) Communications - not applicable.

(5) Fire control circuits - not applicable.

(6) Ventilation - not applicable.

(7) Lighting - Totally inoperable.

(e) Types of equipment most affected.

All types installed.

SECRET

USS LCM - 1

B. Electric Propulsion Rotating Equipment.

Not applicable.

C. Electric Propulsion Control Equipment.

Not applicable.

D. Ship's Service Generators.

Not applicable.

E. Emergency Generators.

Not applicable.

F. Switchboards and Distribution Panels.

Not applicable.

G. Wiring, Wiring Equipment and Wireways.

Totally inoperable due to flooding.

H. Transformers.

Not applicable.

I. Submarine Propelling Batteries.

Not applicable.

J. Portable Batteries.

Batteries partly dislodged from rack and inoperable due to flooding.

K. Motors, Motor Generator Sets and Motor Controllers.

Totally inoperable due to flooding. Mechanically apparently operable.

SECRET

U. S. S. LCM-1

L. Lighting Equipment.

Totally inoperable due to flooding. Mechanically apparently operable.

M. Searchlights.

Not applicable.

N. Degaussing Equipment.

Not applicable.

O. Gyro Compass Equipment.

No gyro equipment on board. Magnesyn compass blown overboard by blast.

P. Sound Powered Telephones.

Not applicable.

Q. Ship's Service Telephones.

Not applicable.

R. Announcing Systems.

Not applicable.

S. Telegraphs.

Not applicable.

T. Indicating Systems.

Not applicable.

U. I. C. and A. C. O. Switchboards.

Not applicable.

SECRET

U. S. S. LCM-1

V. F. C. Switchboards.

Not applicable.

SECRET

U. S. S. LCM-1

SECTION IV

PHOTOGRAPHS

TEST ABLE

SECRET


USS LCM-1



AA-CR-62-1859-2. General view taken one day after test showing craft afloat with bow ramp open and down by the stern as the result of stern tube leakage.

SECRET

USS LCM-1



AA-CR-80-1899-9. General view of craft after recovery.

SECRET

Page 27 of 32 Pages

USS LCM-1

9087



AA-CR-80-1899-11. Dished deck over engine compartment.

SECRET

Page 28 of 32 Pages

USS LCM-1

9087




AA-CR-80-1899-12. Dished after bulwark of conning station.

SECRET

Page 29 of 32 Pages

USS LCM-1

9087



AA-CR-199-2816-7. General view of craft after beaching in preparation for Test B. Bulwarks of conning station slant forward.

SECRET

Page 30 of 32 Pages

USS LCM-1

9087



BA-CR-93-96-9. Interior of tank well before Test A.

SECRET

Page 31 of 32 Pages

USS LCM-1

9087



AA-CR-68-1746-5. Interior of tank well after Test A. Note deflection of bulwark.

SECRET

Page 32 of 32 Pages

USS LCM-1

9087



Defense Special Weapons Agency
6801 Telegraph Road
Alexandria, Virginia 22310-3398

TRC

18 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER
ATTENTION: OMI/Mr. William Bush (Security)

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency has declassified the following reports:

/✓AD-366588 4	XRD-203-Section 12✓
X ——— AD-366589 ✓	XRD-200-Section 9 ✓
AD-366590 ✓	XRD-204-Section 13 ✓
AD-366591 ✓	XRD-183 ✓
/✓AD-366586 ✕	XRD-201-Section 10✓
✓AD-367487 ✓	XRD-131-Volume 2✓
✓✓AD-367516 4	XRD-143✓
✓✓AD-367493 4	XRD-142✓
AD-801410L ✓	XRD-138✓
AD-376831L ✓	XRD-83✓
AD-366759 ✓	XRD-80✓
✓✓AD-376830L ✕	XRD-79✓
/✓AD-376828L 4	XRD-76✓
/✓AD-367464 ✕	XRD-106✓
AD-801404L ✓	XRD-105-Volume 1 ✓
/✓AD-367459 ✕	XRD-100✓

TRC

18 April 1997

Subject: Declassification of Reports

✓✓ AD-367517 ✕	XRD-141 ✓
AD-366762 ✓	XRD-84 ✓
AD-366760 ✓	XRD-81 ✓
AD-366761 ✓	XRD-82 ✓
AD-367501 ✓	XRD-158-Volume 1 ✓
AD-367507L ✓	XRD-152-Volume 4 ✓
✓✓ AD-367495 ✕	XRD-184 ✓
✓✓ AD-367485 ✕	XRD-129 ✓
✓✓ AD-367484 ✕	XRD-128 ✓
✓ AD-367483 ✕	XRD-127 ✓
✓ AD-367482 ✕	XRD-126 ✓
AD-367488 ✓	XRD-132
✓ AD-367480 ✕	XRD-124 ✓
AD-801409L ✓	XRD-135 ✓
✓ AD-367490 ✕	XRD-136 ✓
✓ AD-367492 ✕	XRD-137 ✓
AD-801411L ✓	XRD-139 ✓
✓ AD-367518 ✕	XRD-140 ✓
AD-367515 ✓	XRD-144 ✓
AD-367514 ✓	XRD-145 ✓
✓ AD-367468 ✕	XRD-110-Volume 2 ✓
AD-367513 ✓	XRD-146 ✓
✓ AD-367497 ✕	XRD-162 ✓

TRC

18 April 1997

Subject: Declassification of Reports

AD-801406L ✓ XRD-114✓

In addition, all of the cited reports are now **approved for public release; distribution statement "A" now applies.**

Arldith Jarrett
ARDITH JARRETT
Chief, Technical Resource Center